

Woods Pond Water Quality Committee  
October 13, 2010  
Bridgton, Maine



1. West gate of dam



2. Dam from west headwall

Woods Pond Water Quality Committee  
October 13, 2010  
Bridgton, Maine



3. Dam from east headwall



4. Outlet structure (downstream side)



Woods Pond Water Quality Committee  
October 13, 2010  
Bridgton, Maine



5. Rip-rap at edge of causeway



6. Town beach near edge of parking area

Woods Pond Water Quality Committee  
October 13, 2010  
Bridgton, Maine



7. Exposed roots at town beach



8. Eroded edge of lawn area adjacent to town beach



Woods Pond Water Quality Committee  
October 13, 2010  
Bridgton, Maine



9. Exposed roots near public beach



10. Shrub-scrub, ponded wetland east of town beach



Woods Pond Water Quality Committee  
October 13, 2010  
Bridgton, Maine



11. Edge of forested/shrub-scrub wetland east of town beach



12. Committee members on sand beach at north end of pond



Woods Pond Water Quality Committee  
October 13, 2010  
Bridgton, Maine



13. Erosion noted in ditchline adjacent to Wildwood Road



14. Eroded/exposed cut bank adjacent to ditchline along Wildwood Road



Woods Pond Water Quality Committee  
October 13, 2010  
Bridgton, Maine



15. 60" dia. Culvert outlet on Sucker Brook under Wildwood Road



16. Wildwood Road grade (gravel) adjacent to Sucker Brook bank edge



Woods Pond Water Quality Committee  
October 13, 2010  
Bridgton, Maine



17. View southerly down Wildwood Road (note fine sediments accumulated and migrating off right side of road)



18. Sucker Brook stream bank depicting undercutting



Woods Pond Water Quality Committee  
October 13, 2010  
Bridgton, Maine



19. Sucker Brook within 100' of pond edge. Stream is wider, with slower velocities and more stable banks



20. Example of an old tree-throw on unstable bank near mouth of Sucker Brook on pond edge



Woods Pond Water Quality Committee  
October 13, 2010  
Bridgton, Maine



21. Emergent grasses established on shallow sand bar deposited at mouth of Sucker Brook



22. Wider view of mouth of Sucker Brook, where sediments have been deposited and persistent emergent grasses have become established

Woods Pond Water Quality Committee  
October 13, 2010  
Bridgton, Maine



23. View of man-made access to pond through existing ice berm.



24. Northerly view of large emergent wetland that feeds Sucker Brook, located easterly of Wildwood Road (at old breached dam structure at stream channel)